



Javelin J2xxi Driver & Firmware Update

Thank you for purchasing a Javelin i-Series card printer

This document contains known issues and late breaking news related to this latest version of our software and products as of June 13, 2011.

Supported Configurations

The release of this driver is intended for installation and use with the following Microsoft operating systems:

- Windows® 2000
- Windows® XP
- Windows Server® 2003
- Windows Server® 2008
- Windows Vista® (32-bit/64-Bit)
- Windows 7 (32-bit/64-bit)

This new driver version 1.4.0.5 is a common driver for J2xxi printer models. This release of the driver is intended for installation and use with the following Javelin Card Printers:

Printer models	Minimum firmware revision	Notes
J200i, J230i	V1.31	Includes USB and Ethernet models
** Use of any previous firmware version with this driver version may cause the printer to not operate correctly.		

If your printer type is NOT listed above, this version of our driver is not intended for use with your printer. If your printer is listed above, but the firmware is not equal to or higher than the minimum revision listed above, please visit our web site to download and install the latest version.

http://www.nbstech.com/Support_downloads.html

To check the firmware version of your printer, please look at the last line on the LCD.

Updates since Driver Version V1.4.0.3

1. Auto lid ribbon synchronization button.
2. Ribbon count facility, Cleaning cycle button.
3. YMCKO & YMCKOK auto ribbon detection.
4. Printing time quicker by 1 sec per panel.
5. Different configurations available on YMCKO & YMCKOK settings.
6. Encoding test in driver has security read back feature.
7. Bug fixes – Double decrement of YMCKOK ribbon.

Known Issues

These issues to be resolved in next release

1. Ethernet driver caused s/n to be shown as Ethernet port IP address.
2. Printer will show online in printers/faxes, even if off and unconnected.
3. Win 7 64 bit & USB can cause slow printing.

Updates since Firmware Version 2010.08.26 (V1.21)

1. Better colour correction, allowing lighter colours/shades to be better represented.
2. Vertical dark lines minimized.
3. Multiple prints can be done on J200i

Known Issues

These issues to be resolved in next release

1. S/N on printer does not match S/N in driver.

Technical Assistance

For questions relating to the operation of Javelin equipment you already own, contact your reseller first. Alternately, contact Javelin Technical Support by using one of the following methods:

Americas : Technical Support

Ctc.technicalsupport@nbstech.com

NBS Technologies
10925 Bren Road East
Minneapolis, MN 55343
Phone 952-912-9400

Rest of the world: Technical Support:

technical.support@nbstech.com

NBS Technologies Ltd
B1 Moorfield Point
Slyfield Industrial Park
Guildford
Surrey
Great Britain GU1 1RU
+44 (0) 1483 563200

You can also visit us on the web at www.nbstech.com

Jun 2011